

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Post Trip Truck Inspection: Semios
Project	Truck 35 - Bakersfield	Date of Inspection	January 20, 2021
Inspector Name	Julio Salto	Time of Inspection	05:34 PM

## **INSPECTION ITEMS**

ltem		Comment	Photo
Click "Satisfactory" and enter your Semios branch in the comments section below.	Satisfactory	7125 Meany Av Bakersfield Ca 93308	-
Click "Satisfactory", finish the inspection, and enter the ENDING ODOMETER reading in the comments section below at the end of the day.	Satisfactory	52466	-
Is the vehicle free of any unusual noises?	Satisfactory		-
Are decals clear and visible?	Satisfactory		-
Gauges: Are the fuel gauge, temperature gauge, and dashboard warning light working correctly?	Satisfactory		-
Lights: Are the headlights working correctly?	Satisfactory		-
Lights: Are the brake lights working correctly?	Satisfactory		-
Lights: Are the turn signals working correctly?	Satisfactory		-
Lights: Are the hazard lights working correctly?	Satisfactory		-
Other: Are the windshield wipers in good condition?	Satisfactory		-
Other: Are the fans and defroster in good condition?	Satisfactory		-
Other: Are the brakes in good condition?	Satisfactory		-
Other: Is the parking brake working correctly?	Satisfactory		-
Other: Are the mirrors in good condition?	Satisfactory		-

Other: Is the horn working correctly?	Satisfactory	-
Tires: Are the tires properly inflated?	Satisfactory	-
Tires: Do the tires have adequate tread?	Satisfactory	-
Tires: Is the spare available and properly inflated?	N/A	-
Leaks: Is the vehicle free from oil leaks?	Satisfactory	-
Leaks: Is the vehicle free from all other leaks?	Satisfactory	-
Safety Equipment: Is there a fire extinguisher?	Satisfactory	-
Safety Equipment: Is there a first aid kit?	Satisfactory	-
Safety Equipment: Are there spare bulbs/fuses?	Satisfactory	-
Safety Equipment: Are seat belts in safe condition?	Satisfactory	-
Is the vehicle in acceptable driving condition? If not please describe below	Satisfactory	-
Is there anything else deficient? If so, please describe in the comments section below.	Satisfactory	-