

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Post Trip Truck Inspection: Semios
Project	Truck 54 - Chris F.	Date of Inspection	April 07, 2021
Inspector Name	Chris Figueroa	Time of Inspection	06:19 PM

INSPECTION ITEMS

-
-
-
-
-
-
-
-
-
-
-
-
-
-

Other: Is the horn working correctly?	Satisfactory		-			
Tires: Are the tires properly inflated?	Satisfactory		-			
Tires: Do the tires have adequate tread?	Satisfactory		-			
Tires: Is the spare available and properly inflated?	Satisfactory		-			
Leaks: Is the vehicle free from oil leaks?	Satisfactory		-			
Leaks: Is the vehicle free from all other leaks?	Satisfactory		-			
Safety Equipment: Is there a fire extinguisher?	Satisfactory		-			
Safety Equipment: Is there a first aid kit?	Satisfactory		-			
Safety Equipment: Are there spare bulbs/fuses?	Satisfactory		-			
Safety Equipment: Are seat belts in safe condition?	Satisfactory		-			
Is the vehicle in acceptable driving condition? If not please describe below	Satisfactory		-			
Is there anything else deficient? If so, please describe in the comments section below.	Unsatisfactory	steering wheel seems to be bouncing around when over 60mph	-			
UNSATISFACTORY ITEMS						
Photo	Comment	Corrective Action				
-						