



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Vehicle Inspection Not Required
Project	Truck 73 (69146D3) - Turlock	Date of Inspection	December 22, 2021
Inspector Name	Rodolfo Barboza	Time of Inspection	06:29 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the BEGINNING ODOMETER reading in the comments section below.	Satisfactory	17704	-
Click N/A if DOT inspection is not required.	N/A		-