



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Silverwood Landscape Construction Inc.	Type of Inspection:	Skid Steer Loader #512
Project	Laguna Niguel	Date of Inspection	April 09, 2019
Inspector Name	Manuel Rocha	Time of Inspection	02:35 PM

INSPECTION ITEMS

Item		Comment	Photo
Hour meter reading available? (Enter reading in comments below)	Satisfactory	515.6 horas	-
Is the ignition and electrical system working correctly? Are all gauges and instruments visible and working correctly?	Satisfactory		-
Are the warning lights (and lights, if applicable) working correctly?	Satisfactory		-
Are the brakes working correctly?	Satisfactory		-
Is the moving alarm audible and working correctly?	Satisfactory		-
Does the engine sound normal?	Satisfactory		-
Do the steering controls all work normally, including response time?	Satisfactory		-
Is the instrumentation operating normally and legible?	Satisfactory		-
Do the levers (switches, toggles, joysticks, sticks, etc) work smoothly and safely?	Satisfactory		-
Is the exhaust in a safe condition with no excessive smoke, sparks or flames?	Satisfactory		-
Other items?	Satisfactory		-
Are the safety decks / warning stickers visible and legible?	Satisfactory		-
Is the operators manual in place?	Satisfactory		-
Is the air filter free of dust and trash build up?	Satisfactory		-
Is the chassis free of structural damage? Is the turntable lubricated?	Satisfactory		-

Is the bucket and teeth in safe condition free of structural damage and/or wear	Satisfactory		-
Is the coolant system free of leaks and damage? is the coolant level good?	Satisfactory		-
Is the engine oil level good? Are there any leaks?	Satisfactory		-
Are the engine belts free of wear and damage?	Satisfactory		-
Is the fuel system in good condition, including the fuel level?	Satisfactory		-
Is the hydraulic system in good condition? Are the hydraulic level and filters good?	Satisfactory		-
Are the tracks / wheels in good condition and free of wear and damage?	Satisfactory		-
Is the operator cab clean, items secure, and free of damage?	Satisfactory		-