



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Silverwood Landscape Construction Inc.	Type of Inspection:	Cal/OSHA Heat Illness Replenishment Form
Project	Uptown Newport	Date of Inspection	April 08, 2019
Inspector Name	Albis Cruz Suazo	Time of Inspection	06:18 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the job site address / cross streets	Satisfactory	Up town Newport jamboree and Fairchild	-
Is there a system in place to monitor the temperature? Please describe below	Satisfactory	Celular	-
Is sufficient shade available for the site? Describe below the type of shade and where it is located	Satisfactory		-
Is there a water indicator management system in place that triggers the need for replenishment? Describe it in the comments	Satisfactory	If jar is less than 1/4	-
Is sufficient drinking water available? Enter the number of containers and where they are located	Satisfactory	5 gallons of water on truck 161	-
Is someone in charge of calling 911 in the event of an emergency? Enter name in comments	Satisfactory	Albis Cruz	-
Is someone in charge of the Heat Illness Program on site? Enter name in comments	Satisfactory		-
Is someone in charge of shade set up? Enter name in comments	Satisfactory		-
Is someone in charge of replenishment? Enter name in comments	Satisfactory		-
Are there any special notes or comments?	Satisfactory		-