



CONFINED SPACE PERMIT

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Ultimate Internet Access	Project	RC 2
Time	09:45 AM	Date	May 07, 2024
Duration	01	Supervisor Name	Edwin Jaggli

SECTION 1

SITE LOCATION

10611 acacia st Rancho Cucamonga

DESCRIPTION OF CONFINEDSPACE

Manhole

NATURE OF WORK/ REASON FOR ENTRY

Ridding

OTHER PERMITS

SECTION 2

PERMIT PULLED

Pull Date : **May 07, 2024**

Pull Time : **09:45 AM**

Pull Duration : **01**

PERMIT CLOSED

Closed Date : **May 07, 2024**

Closed Time : **10:11 AM**

RESCUE AND EMERGENCY RESPONSE

No Entry Rescue

Tripod

Entry Rescue Team

SECTION 3

Atmospheric Hazard Identification

Air Monitoring location specified Middle

Ventilation

Adequate pre-entry ventilation has been completed NATURAL

SECTION 4

INITIAL TEST BEFORE MECHANICAL VENTILATION OR ENTRY

LEL	0
Oxygen	20.8
H2S	0
CO	0

Additional Reading (10:06 AM)

LEL	10
Oxygen	21.3
H2S	10
CO	10

ATTENDANT(S)

Steve Corona

AUTHORIZED ENTRANTS

Noe Delgado

COMMUNICATION SYSTEM

Verbal

Radio

Phone

Sight

OTHER HAZARDS

Poor Lighting

PPE REQUIRED

Head Protection

Eye Protection

Respiratory Protection

Body Protection

Fall Protection

SUPERVISOR SIGNATURE

A handwritten signature in black ink, appearing to be 'C. J. Smith'.

CLOSED SIGNATURE

A handwritten signature in black ink, appearing to be 'C. J. Smith'.