

### **CONFINED SPACE PERMIT**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Ultimate Internet Access	Project	RC 2
Time	08:06 AM	Date	May 08, 2024
Duration	01	Supervisor Name	Carlos Aguilar

### **SECTION 1**

#### SITE LOCATION

10860 Sixth St Rancho Cucamonga, CA 91730 United States

#### **DESCRIPTION OF CONFINEDSPACE**

Manhole

#### NATURE OF WORK/ REASON FOR ENTRY

Rodding conduit

#### **OTHER PERMITS**

## **SECTION 2**

#### **PERMIT PULLED**

Pull Date : **May 08, 2024** Pull Time : **08:06 AM** Pull Duration : **01** 

PERMIT CLOSED

Closed Date: May 08, 2024 Closed Time: 08:47 AM

#### RESCUE AND EMERGENCY RESPONSE

**No Entry Rescue** 

Tripod Wench

**Entry Rescue Team** 

### **SECTION 3**

### **Atmospheric Hazard Identification**

Air Monitoring location specified Top

### **SECTION 4**

#### INITIAL TEST BEFORE MECHANICAL VENTILATION OR ENTRY

LEL

Oxygen 20.8

H2S

CO

LEL 0

Oxygen

H2S

CO

## ATTENDANT(S)

### **Carlos Aguilar**

**Saul Nieves** 

### **AUTHORIZED ENTRANTS**

**Raul Medel** 

## **COMMUNICATION SYSTEM**

Radio

Verbal

**Phone** 

**Sight** 

# **OTHER HAZARDS**

**Poor Lighting** 

### **PPE REQUIRED**

**Head Protection** 

**Eye Protection** 

**Respiratory Protection** 

**Body Protection** 

**Fall Protection** 

# **SUPERVISOR SIGNATURE**

AND THE RESIDENCE OF THE PARTY OF THE PARTY

# **CLOSED SIGNATURE**

