



# CONFINED SPACE PERMIT

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Ultimate Internet Access	<b>Project</b>	Rancho 5
<b>Time</b>	11:51 AM	<b>Date</b>	July 11, 2024
<b>Duration</b>	01	<b>Supervisor Name</b>	Carlos Aguilar

## SECTION 1

### SITE LOCATION

8794 Lion St Rancho Cucamonga, CA 91730 United States

### DESCRIPTION OF CONFINEDSPACE

Manhole

### NATURE OF WORK/ REASON FOR ENTRY

Conduit Identifying

### OTHER PERMITS

## SECTION 2

### PERMIT PULLED

Pull Date : **July 11, 2024**

Pull Time : **11:51 AM**

Pull Duration : **01**

### PERMIT CLOSED

Closed Date : **July 11, 2024**

Closed Time : **12:26 PM**

### RESCUE AND EMERGENCY RESPONSE

No Entry Rescue

Entry Rescue Team

## SECTION 4

### INITIAL TEST BEFORE MECHANICAL VENTILATION OR ENTRY

LEL

Oxygen

20.8

H2S

CO

## ATTENDANT(S)

Pete Valdez

Lisando Briseno

## AUTHORIZED ENTRANTS

Bryan Godinez-Lopez

## COMMUNICATION SYSTEM

Radio

Verbal

Phone

Sight

## PPE REQUIRED

Head Protection

Eye Protection

Respiratory Protection

Body Protection

Fall Protection

## SUPERVISOR SIGNATURE

CA

**CLOSED SIGNATURE**

CA