



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Woodside Homes: Northern California	Type of Inspection:	General Construction
Project	Altair	Date of Inspection	August 09, 2022
Inspector Name	Bill Johnson	Time of Inspection	03:07 PM

INSPECTION ITEMS

Item		Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory		-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory		-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is Personal Protective Equipment being worn as required?	Satisfactory		-
Are scaffolding safety procedures being followed?	N/A	There's no scaffolding on the job at this time	-
Are hand and power tools being used safely?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A	There is no need for fall protection on the job site at this time	-
Is trenching & excavation work being done safely?	N/A	There is no trenching being done on the job site at this time	-
Are confined space safety procedures being followed?	Satisfactory		-
Are scissor lifts / elevated platforms being used safely?	N/A	There are no scissor lifts on the job at this time	-
Are boom lifts and other aerial devices being used safely?	N/A	There are no boom lifts on the job site	-
Is heavy equipment being used safely?	N/A	There was no heavy equipment on the job site at this time	-

Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	N/A	There is no work being done on roofs on our job site at this time	-
Is demolition work being done safely?	N/A	There was no demolition work being done on the job site at this time	-
Are all other tasks being performed safely?	Satisfactory		-