



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Woodside Homes: Northern California	Type of Inspection:	Cal/OSHA Scaffold
Project	Altair	Date of Inspection	June 25, 2024
Inspector Name	Denis Dzik	Time of Inspection	01:38 PM

INSPECTION ITEMS

Item	Comment	Photo
Are erectors and dismantlers under the supervision of a qualified erector?	N/A	-
Is the scaffold safe to use in every other way?	Satisfactory	-
Are only trained users being allowed on the scaffold?	Satisfactory	-
if more than three times the width of the base, is the scaffold braced per the manufacturer and OSHA instructions?	Satisfactory	-
Are toe-boards installed where required, including above entranceways and where others may pass underneath?	Unsatisfactory	-
is there safe access to each working level of the scaffold?	Satisfactory	-
Are guardrails correctly installed on platforms above 7 1/2 feet? (Note: Some Mfg's require rails at any height)	Satisfactory	-
Do planks overlap supports (or otherwise secured) per manufacturer and OSHA instructions?	Satisfactory	-
Are planks in safe condition?	Satisfactory	-
Are platforms fully planked with no more than a 1" gap between planks?	Satisfactory	-
Are cross braces installed per the manufacturer and OSHA instructions?	Satisfactory	-
Is the scaffold plumb and level?	Satisfactory	-
Are base plates installed and appropriately nailed to mud sills (if sills are required)?	Satisfactory	-
Is the scaffold on a secure foundation?	Satisfactory	-

If over 36 feet or 3 stories, has an OSHA permit for scaffolding been pulled and notification of activity given to the local OSHA office?	N/A		-
Are daily inspections being done by a competent person?	Satisfactory		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-	Few boards got displaced	Boards are back in place