



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                                     |                            |                      |
|-----------------------|-------------------------------------|----------------------------|----------------------|
| <b>Company</b>        | Woodside Homes: Northern California | <b>Type of Inspection:</b> | General Construction |
| <b>Project</b>        | Berkshire                           | <b>Date of Inspection</b>  | July 13, 2022        |
| <b>Inspector Name</b> | Jose Garcia                         | <b>Time of Inspection</b>  | 11:20 AM             |

## INSPECTION ITEMS

| Item   |              | Comment | Photo |
|--|--------------|---------|-------|
| is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? | Satisfactory |         | -     |
| Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)    | Satisfactory |         | -     |
| Is drinking water and shade set up sufficient for the amount of workers?               | Satisfactory |         | -     |
| Are emergency and labor law postings in place?   | Satisfactory |         | -     |
| Is Personal Protective Equipment being worn as required?                               | Satisfactory |         | -     |
| Are scaffolding safety procedures being followed?                                      | Satisfactory |         | -     |
| Are hand and power tools being used safely?  | Satisfactory |         | -     |
| Is good housekeeping being maintained?   | Satisfactory |         | -     |
| Is fall protection in place where required?  | Satisfactory |         | -     |
| Is trenching & excavation work being done safely?                                      | Satisfactory |         | -     |
| Are confined space safety procedures being followed?                                   | Satisfactory |         | -     |
| Are scissor lifts / elevated platforms being used safely?                              | Satisfactory |         | -     |
| Are boom lifts and other aerial devices being used safely?                             | N/A          |         | -     |
| Is heavy equipment being used safely?  | Satisfactory |         | -     |
| Are electrical items being used safely?  | Satisfactory |         | -     |

|  |              |          |   |
|--|--------------|----------|---|
| Are roofing operations being performed safely? | Satisfactory | all good |  A photograph showing a construction worker in a yellow safety vest and white hard hat standing on a roof, working on the shingles under a clear blue sky. |
| Is demolition work being done safely?          | N/A          |          | -   |
| Are all other tasks being performed safely?    | Satisfactory |          | -   |