



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Woodside Homes: Northern California	<b>Type of Inspection:</b>	Log a Safety Observation
<b>Project</b>	Brady vineyards	<b>Date of Inspection</b>	June 27, 2024
<b>Inspector Name</b>	Leo Martinez	<b>Time of Inspection</b>	01:44 PM

## INSPECTION ITEMS

Item	Comment	Photo
Ladder Safety - Log a Safety Observation	Satisfactory	-
Fall Protection - Log a Safety Observation	Satisfactory	-
Scaffolding - Log a Safety Observation	Satisfactory	-
Equipment - Log a Safety Observation	Satisfactory	-
COVID Protocols / Social Distancing - Log a Safety Observation	Satisfactory	-
PPE/Hard Hats - Log a Safety Observation	Satisfactory	-
OTHER - Click Satisfactory to log a good safety observation, or click unsatisfactory to log a negative safety observation.	Unsatisfactory	-

## UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-	missing cover plate for temp outlet	Install missing cover plate in temp garage outlet lot 41