

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Accel Framing & General Contracting

**PROJECT:**  
Benning Residence



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** JEREMY CHAVEZ  
**DATE :** DECEMBER 18, 2024  
**CITY :** CORONADO  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>54</b> Items Inspected	<b>22</b> Satisfactory	<b>1</b> Unsatisfactory	<b>31</b> N/A
------------------------------	---------------------------	----------------------------	------------------

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Site walked with Guillermo.	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>N/A</b>
<b>Tailgate Meetings</b>	<b>N/A</b>
<b>Sub-Contractor Meetings</b>	<b>N/A</b>
<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	

Jobsite posting have been provided.



**Emergency / Other Postings** **Satisfactory**

**First Aid / CPR Certification** **N/A**

**Emergency Items**

**Access / Egress** **Satisfactory**

**Elevator for Hoisting Workers (if needed)** **N/A**

**Fire Extinguisher(s)** **Satisfactory**

**First Aid Kit(s)** **Satisfactory**

**Eye Wash Station** **Satisfactory**

**Personnel Hoist** **N/A**

**Other Fire Fighting Equipment (If needed)** **N/A**

**General Items**

**Restrooms** **Satisfactory**

**Comment**

The restrooms and handwashing station appear to be maintained in a sanitary condition.



**Hand Washing Stations**

**Satisfactory**

**Waste Containers**

**Satisfactory**

**Potable Water**

**Satisfactory**

**Shade**

**N/A**

## Tools & Equipment

**Power Tools**

**Satisfactory**

### Comment

Tools observed had the manufacturer's required safety elements present and unaltered.



**Hand Tools**

**Satisfactory**

**Powder Actuated Tools**

**N/A**

**Pneumatic Nailers**


**N/A**

**Mobile Elevated Work Platforms (MEWP's)**

**N/A**


Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A

## Operations

Personal Protective Equipment	Satisfactory
<b>Comment</b>	
<p>Employees were observed wearing the required PPE, including ANSI rated safety glasses.</p>	

Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	Satisfactory
<b>Comment</b>	

A general reminder was provided to install guard rails once this section of the structure has been framed. The employees are well aware of the need for guard rails and will provide them as soon as possible.



**Floor / Wall Openings**

**N/A**

**Supported Scaffolding**

**N/A**

**Mobile Scaffolding**

**N/A**

**Suspended Scaffolding**

**N/A**

**Confined Spaces**

**N/A**

**Impalement Hazards**

**Satisfactory**

**Comment**

Impairment protection was observed to be installed where required.



**Traffic Control**

**N/A**



**Roofing Operations**

**N/A**

**Housekeeping**

**Satisfactory**

**Comment**

<p>Overall, good job with housekeeping throughout the project.</p>	
<p>On the second floor, there is a need for attention with chords and hoses and walkways. Again, the employees are well aware of the hazards, and are in the process of organizing materials.</p>	

<p><b>Demolition</b></p>	<p><b>N/A</b></p>
<p><b>Silica Control</b></p>	<p><b>N/A</b></p>
<p><b>Rigging Operations</b></p>	<p><b>N/A</b></p>
<p><b>Hot Work</b></p>	<p><b>N/A</b></p>
<p><b>Electrical Safety</b></p>	<p><b>Satisfactory</b></p>
<p><b>Lockout / Tagout</b></p>	<p><b>N/A</b></p>
<p><b>Stairways, Ramps, Runways</b></p>	<p><b>Unsatisfactory</b></p>
<p><b>Comment</b></p>	

Please ensure stairs with four or more risers have at least one handrail installed.



**Other Items (that were observed)**

**N/A**