

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Accel Framing & General Contracting

**PROJECT:**  
Mission Village 2696



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** JEREMY CHAVEZ  
**DATE :** SEPTEMBER 16, 2024  
**CITY :** SAN DIEGO  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

**53**  
Items Inspected

**24**  
Satisfactory

**4**  
Unsatisfactory

**25**  
N/A

# INSPECTION ITEMS

## Documentation

**Site Contact**

**Satisfactory**

**Comment**

Site walked with Jim Houle.

**Safety Program (Including IIPP)**

**Satisfactory**

**Heat Illness Prevention Program**

**Satisfactory**

**Safety Data Sheets**


**Satisfactory**

**Daily Inspections**

**Unsatisfactory**

**Comment**

The daily inspection is being completed, however, the pre-task portion must also be completed.




**Tailgate Meetings**

**Satisfactory**

**Comment**

Tailgates are being conducted at least every 10 working days



**Sub-Contractor Meetings**

**N/A**

**OSHA Permits**

**Satisfactory**

**Labor Law Postings**

**Satisfactory**

**Comment**

Labor law postings are in place as required.



**Emergency / Other Postings**

**Satisfactory**

**Comment**

Emergency and medical clinic locations are required to be posted



**First Aid / CPR Certification**

**Satisfactory**

## Emergency Items

**Access / Egress** Satisfactory

**Elevator for Hoisting Workers (if needed)** N/A

**Fire Extinguisher(s)** Unsatisfactory

**Comment**

A fire extinguisher does not have its monthly inspection documented. Please ensure fire extinguishers are inspected monthly.



**First Aid Kit(s)** Satisfactory

**Comment**

A first aid kit is readily available for employees on site.



**Eye Wash Station** Satisfactory

**Other Fire Fighting Equipment (If needed)** N/A

## General Items

**Restrooms** Satisfactory

**Comment**

The restrooms and hand washing stations appeared to be maintained in a sanitary condition.



**Hand Washing Stations**

**Satisfactory**

**Waste Containers**

**Satisfactory**

**Potable Water**

**Satisfactory**

**Comment**

Plenty of cool potable water is available for employees.



**Shade**

**Satisfactory**

**Comment**

A shaded rest area has been provided for employees.



**Tools & Equipment**

**Power Tools**

**Satisfactory**

**Comment**

Power tools were observed to have the manufacturer's required safety elements present and unaltered.



**Hand Tools**

**Satisfactory**

**Powder Actuated Tools**

**N/A**

**Pneumatic Nailers**

**Unsatisfactory**

**Comment**

Please ensure nail guns are disconnected from their hose when not in use.



**Mobile Elevated Work Platforms (MEWP's)**

**N/A**

**Powered Industrial Trucks**

**Satisfactory**

**Heavy Mobile Equipment (Excavators, Loaders, etc)**

**N/A**

**Cranes**

**N/A**

**Cylinder Storage**

**N/A**

**Ladders**

**Satisfactory**

## Operations

### Personal Protective Equipment

**Satisfactory**

#### Comment

Employees were observed wearing the required PPE, including ANSI rated safety glasses.



### Trenching & Excavation

**N/A**

### Fall Protection

**N/A**

### Guardrails

**N/A**

### Floor / Wall Openings

**N/A**

### Supported Scaffolding

**N/A**

### Mobile Scaffolding

**N/A**

### Suspended Scaffolding

**N/A**

### Confined Spaces

**N/A**

### Impalement Hazards

**Unsatisfactory**

#### Comment

Another trade has left uncapped rebar. Please ensure the rebar is capped and employees are protected from impalement hazards.



<b>Traffic Control</b>	<b>N/A</b>
<b>Roofing Operations</b>	<b>N/A</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>N/A</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>