

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Air Conditioning Solutions, Inc.

PROJECT:
6080 Center Dr.



INSPECTION TYPE:
General Construction

INSPECTOR : JUSTYN BLANCHARD
DATE : APRIL 26, 2024
CITY : LOS ANGELES
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

52 Items Inspected	23 Satisfactory	0 Unsatisfactory	29 N/A
------------------------------	---------------------------	----------------------------	------------------

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Comment	
Jeremy Smith	-
Safety Program (Including IIPP)	Satisfactory
Comment	
This is in the SCC app.	-
Heat Illness Prevention Program	Satisfactory
Comment	
This is in the IIPP	-
Safety Data Sheets	Satisfactory
Comment	
This is in the SCC app.	-
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Comment	

This is in the SCC app.	-
-------------------------	---

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

Comment	
----------------	--

This is accessible via a secondary app.	-
---	---

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items	
------------------------	--

Access / Egress	Satisfactory
------------------------	---------------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment	
----------------	--

Fire extinguisher is on the truck.	-
------------------------------------	---

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

First aid kit is in stock and on the truck.	-
---	---

Eye Wash Station	N/A
-------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items	
----------------------	--

Restrooms	Satisfactory
------------------	---------------------

Comment	
----------------	--

Building restrooms are accessible.	-
------------------------------------	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment	
----------------	--

In the building restrooms.	-
----------------------------	---

Waste Containers	Satisfactory
-------------------------	---------------------


Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------

Comment	
Building provides shade.	-

Tools & Equipment

Power Tools	Satisfactory
--------------------	---------------------

Comment	
Power tools were seen to be in good condition.	

Hand Tools	Satisfactory
-------------------	---------------------

Comment	
Hand tools were seen to be in good condition.	-

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------


Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
----------------	---------------------

Comment

Ladders were seen to be in good condition and are being used properly. Lifts were also being used to installed the air duct system.



Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment

PPE is being worn as required.

-

Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	N/A
---------------------------	------------

Traffic Control	N/A
------------------------	------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment	
ACS work area is very clean.	-

Demolition	N/A
-------------------	------------

Silica Control	N/A
-----------------------	------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	N/A
--------------------------	------------

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	N/A
----------------------------------	------------

Other Items (that were observed)	Satisfactory
---	---------------------

Comment	
<p>Work being done today is installed the air duct system throughout the 9th floor.</p>	