

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Air Conditioning Solutions, Inc.

**PROJECT:**  
6080 Center Dr.



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** JUSTYN BLANCHARD  
**DATE :** APRIL 26, 2024  
**CITY :** LOS ANGELES  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>52</b> Items Inspected	<b>23</b> Satisfactory	<b>0</b> Unsatisfactory	<b>29</b> N/A
------------------------------	---------------------------	----------------------------	------------------

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Bobby Lepold	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Comment</b>	
This is in the SCC app.	-
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	
This is in the IIPP	-
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Comment</b>	
This is in the SCC app.	-
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>N/A</b>
<b>OSHA Permits</b>	<b>N/A</b>
<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	

This is in the SCC app.	-
-------------------------	---

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>Comment</b>	
----------------	--

This is accessible via a secondary app.	-
---	---

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
-----------------------------	---------------------

<b>Comment</b>	
----------------	--

Fire extinguisher on site is up to date.



<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
----------------	--

First aid kit is in stock and on the truck.

-

<b>Eye Wash Station</b>	<b>N/A</b>
-------------------------	------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Comment</b>	
----------------	--

Building restrooms are accessible.

-

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Comment</b>	
----------------	--

In the building restrooms.	-
----------------------------	---

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

<b>Comment</b>	
----------------	--

Building provides shade.	-
--------------------------	---

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Comment</b>	
----------------	--

Power tools were seen to be in good condition.	-
--	---

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Comment</b>	
----------------	--

Hand tools were seen to be in good condition.	-
---	---

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------


<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>		<b>Satisfactory</b>
<b>Comment</b>		
Ladders were seen to be in good condition and are being used properly. Work is being done installing piping for the AC units.		

## Operations

<b>Personal Protective Equipment</b>		<b>Satisfactory</b>
<b>Comment</b>		
PPE is being worn as required.	-	

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>N/A</b>
------------------------	------------

<b>Guardrails</b>	<b>N/A</b>
-------------------	------------

<b>Floor / Wall Openings</b>	<b>N/A</b>
------------------------------	------------

<b>Supported Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Mobile Scaffolding</b>	<b>N/A</b>
---------------------------	------------

<b>Suspended Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------

<b>Impalement Hazards</b>	<b>N/A</b>
---------------------------	------------

<b>Traffic Control</b>	<b>N/A</b>
------------------------	------------

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------


<b>Comment</b>	
ACS work area is very clean.	-

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Silica Control</b>	<b>N/A</b>
-----------------------	------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Hot Work</b>	<b>Satisfactory</b>
-----------------	---------------------

<b>Comment</b>	
Any hot work being done is brazing. Hot work procedures are being followed. Fire extinguishers are near by for this.	

<b>Electrical Safety</b>	<b>N/A</b>
--------------------------	------------

<b>Lockout / Tagout</b>	<b>N/A</b>
-------------------------	------------

<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
----------------------------------	------------

<b>Other Items (that were observed)</b>	<b>N/A</b>
---	------------