

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Ashwood Construction, Inc.

PROJECT:
River Grove



INSPECTION TYPE:
General Construction

INSPECTOR : KIM BURGESS
DATE : SEPTEMBER 27, 2024
CITY : OAKHURST
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	32 Satisfactory	0 Unsatisfactory	21 N/A
------------------------------	---------------------------	----------------------------	------------------

Updated workplace violence and heat illness for indoor located in safety book.

All postings visible in trailer.

Water supply in compliance as temps remain above 80 degrees.

Reliable no violations.

West Coast countertops silica items safe.

DW Langley using water when cutting material.

Walked site with Adam. Great job on site today.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Comment	

<p>Good job with completing daily inspections</p>	
---	---

<p>Tailgate Meetings</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

<p>Sub-Contractor Meetings</p>	<p>Satisfactory</p>
---------------------------------------	----------------------------

<p>OSHA Permits</p>	<p>Satisfactory</p>
----------------------------	----------------------------

<p>Labor Law Postings</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

<p>Emergency / Other Postings</p>	<p>Satisfactory</p>
--	----------------------------

<p>First Aid / CPR Certification</p>	<p>Satisfactory</p>
---	----------------------------

<p>Comment</p>	
<p>Certifications current.</p>	<p>-</p>

Emergency Items

<p>Access / Egress</p>	<p>Satisfactory</p>
-------------------------------	----------------------------

<p>Elevator for Hoisting Workers (if needed)</p>	<p>N/A</p>
---	-------------------

<p>Fire Extinguisher(s)</p>	<p>Satisfactory</p>
------------------------------------	----------------------------

<p>First Aid Kit(s)</p>	<p>Satisfactory</p>
--------------------------------	----------------------------

<p>Eye Wash Station</p>	<p>N/A</p>
--------------------------------	-------------------

<p>Other Fire Fighting Equipment (If needed)</p>	<p>N/A</p>
---	-------------------

General Items

Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory

Tools & Equipment

Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Platforms (MEWP's)	Satisfactory
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

Comment	
Ladders were found to be in good condition and are being inspected daily	-

Operations	
Personal Protective Equipment	Satisfactory
Comment	
All PPE being worn	-
Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	Satisfactory
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Comment	

Silca being controlled (ex. water or vacuum)	
--	---

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Other Items (that were observed)	N/A
---	------------