

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Ashwood Construction, Inc.

**PROJECT:**  
Riverwalk



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** KIM BURGESS  
**DATE :** APRIL 19, 2024  
**CITY :** PASO ROBLES  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>52</b> Items Inspected	<b>33</b> Satisfactory	<b>1</b> Unsatisfactory	<b>18</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Little activity on site. Confirmed daily inspections and tailgate meetings were completed. Postings present in office. Water supply good. American electrical on site. Hard hat violation was corrected on site. Incident report was completed.

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>


## Emergency Items

<b>Eye Wash Station</b>	<b>N/A</b>
-------------------------	------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
-----------------------------	---------------------

<b>Comment</b>	
Fire extinguishers present thru out buildings on site.	

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

## General Items

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

## Tools & Equipment

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Power Tools	Satisfactory
Cranes	N/A
Hand Tools	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Powder Actuated Tools	N/A
Cylinder Storage	N/A
Pneumatic Nailers	N/A
<b>Operations</b>	
Floor / Wall Openings	Satisfactory
Other Items (that were observed)	N/A
Rigging Operations	N/A
Traffic Control	N/A
Supported Scaffolding	Satisfactory
Personal Protective Equipment	Unsatisfactory
<b>Comment</b>	
American electrical not wearing hard hat was corrected on site	-
Hot Work	N/A

<b>Roofing Operations</b>	<b>N/A</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Trenching &amp; Excavation</b>	<b>Satisfactory</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Fall Protection</b>	<b>N/A</b>
<b>Comment</b>	
No workers working above trigger heights	-
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Demolition</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Guardrails</b>	<b>Satisfactory</b>
<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
<b>Silica Control</b>	<b>Satisfactory</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>