SAFETY INSPECTION REPORT

CONDUCTED FOR:

Ashwood Construction, Inc.

PROJECT:

Riverwalk



INSPECTION TYPE:

General Construction

INSPECTOR: KIM BURGESS DATE: FEBRUARY 21, 2025 CITY: PASO ROBLES

STATE: CA

SITE CONTACT: TANNER

ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 52 Items Inspected 30 Satisfactory 1 Unsatisfactory N/A

Walked site with Tanner.

SPURR
GIBSON
FERGUSON
AMERICAN ELECTRICAL
ELITE
SUNSET

Items observed during inspection:

Permanent guard rails are being set thru out site, however during inspection no temporary rails present at several openings. They will be set. If not able to set today stairs will be blocked so no access until rails are installed.

No scaffolding on site.

Restrooms and hand wash stations in compliance.

Stairways have guard rails in place.

Elevators installed, doors and windows installed.

Roof work completed.

Moved office to a unit in building. Will set all required postings.

INSPECTION ITEMS

Documentation	
Safety Program (Including IIPP)	Satisfactory
Comment	-
Safety Program is available	-

Heat Illness Prevention Program	Satisfactory
Comment	-
Heat Illness Prevention Program is available and site specific information is completed.	-

Safety Data Sheets Satisfactory

Daily Inspections	Satisfactory
Comment	-
Daily inspections are being performed	-

Tailgate Meetings	Satisfactory
Comment	-
Tailgates are being conducted at least every 10 working days	-

Sub-Contractor Meetings

Satisfactory

OSHA Permits Satisfactory

Comment

OSHA 300 log will be posted



Labor Law Postings	Satisfactory
Comment	-

Satisfactory

2025 labor law posters in place.

General Items

Restrooms



Emergency / Other Postings	Satisfactory
Comment	-
Will mark location for emergency evacuation plan.	-
First Aid / CPR Certification	Satisfactory
Comment	-
First aid current	-
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Comment	Ashwood
First aid kit fully stocked.	-
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A

Comment	-
Restroom maintained.	-
Hand Washing Stations	Satisfactory
Comment	-
Soap, towels and water in compliance.	-
Waste Containers	Satisfactory
Comment	-
Waste containers provided	-
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Comment	-
All power tools and equipment in good functional order	-
Hand Tools	Satisfactory
Comment	-
Powers tools are UL approved	-
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory

N/A **Cranes Cylinder Storage** N/A Ladders **Satisfactory** Operations Satisfactory **Personal Protective Equipment Trenching & Excavation** N/A **Fall Protection** N/A **Guardrails Unsatisfactory** Comment Temporary guard rails will be set until permanent rails installed. N/A Floor / Wall Openings **Supported Scaffolding** N/A N/A **Mobile Scaffolding** N/A **Suspended Scaffolding** N/A **Confined Spaces Impalement Hazards Satisfactory**

Comment

Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement

Comment



Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hat Wards	
Hot Work	N/A
Electrical Safety	N/A Satisfactory

Guard rails set



Other Items (that were observed)

N/A