

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Ashwood Construction, Inc.

PROJECT:
Santa Fe Commons II



INSPECTION TYPE:
General Construction

INSPECTOR : FRANCISCO ROMERO
DATE : JULY 16, 2024
CITY : TULARE
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	40 Satisfactory	0 Unsatisfactory	13 N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival, I went to their new location on the site, I spoke Mr Steels and we talked briefly, I did a safety meeting with the guys and he allowed me to do inspection.

- Subs on site
- Dudley Landscape
- Holders Plumbing
- Award painting

During the inspection, I found no violations. I will provide report for their review.


INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory


Labor Law Postings**Satisfactory****Emergency / Other Postings****Satisfactory****First Aid / CPR Certification****Satisfactory****Emergency Items****Access / Egress****Satisfactory****Elevator for Hoisting Workers (if needed)****N/A****Fire Extinguisher(s)****Satisfactory****First Aid Kit(s)****Satisfactory****Eye Wash Station****Satisfactory****Other Fire Fighting Equipment (If needed)****N/A****General Items****Restrooms****Satisfactory****Hand Washing Stations****Satisfactory****Waste Containers****Satisfactory****Potable Water****Satisfactory****Shade****Satisfactory****Tools & Equipment****Power Tools****Satisfactory**

Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	Satisfactory
Ladders	Satisfactory

Operations

Personal Protective Equipment	Satisfactory
Comment	
Found all workers wearing all their safety gear on site.	

Trenching & Excavation	N/A
Fall Protection	Satisfactory
Guardrails	Satisfactory

Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
Found all rebar that was capped properly and securely on site	
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A

Electrical Safety	Satisfactory
Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A