

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Ashwood Construction, Inc.

PROJECT:
Sunrise Villas



INSPECTION TYPE:
General Construction

INSPECTOR : KIM BURGESS
DATE : SEPTEMBER 18, 2024
CITY : PASO ROBLES
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	30 Satisfactory	1 Unsatisfactory	22 N/A
------------------------------	---------------------------	----------------------------	------------------

Not a lot of activity on site today.

Confirmed dailies completed. Tailgate meetings completed.

Walked site. Stairways in compliance.

Damaged extension cord will be removed.

Ashwood good job being proactive on job site, correcting violations when observed.

- COSCO
- SPURR
- AIRPORT SPECIALTIES

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
---------------------	---------------------

Safety Program (Including IIPP)	Satisfactory
--	---------------------

Heat Illness Prevention Program	Satisfactory
--	---------------------

Comment

Ashwood has fans in place and in compliance with indoor heat regulations.




Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

Emergency Items

Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
Comment	
Fire extinguisher located in office as well as thru out site.	-

First Aid Kit(s)	Satisfactory
Comment	

<p>First aid kit in compliance.</p>	
-------------------------------------	---

<p>Eye Wash Station</p>	<p>N/A</p>
--------------------------------	-------------------

<p>Other Fire Fighting Equipment (If needed)</p>	<p>N/A</p>
---	-------------------

General Items

<p>Restrooms</p>	<p>Satisfactory</p>
-------------------------	----------------------------

<p>Hand Washing Stations</p>	<p>Satisfactory</p>
-------------------------------------	----------------------------

<p>Waste Containers</p>	<p>Satisfactory</p>
--------------------------------	----------------------------

<p>Potable Water</p>	<p>Satisfactory</p>
-----------------------------	----------------------------

<p>Shade</p>	<p>Satisfactory</p>
---------------------	----------------------------

Tools & Equipment

<p>Power Tools</p>	<p>Satisfactory</p>
---------------------------	----------------------------

<p>Hand Tools</p>	<p>Satisfactory</p>
--------------------------	----------------------------

<p>Powder Actuated Tools</p>	<p>N/A</p>
-------------------------------------	-------------------

<p>Pneumatic Nailers</p>	<p>N/A</p>
---------------------------------	-------------------

<p>Mobile Elevated Work Platforms (MEWP's)</p>	<p>Satisfactory</p>
---	----------------------------

Powered Industrial Trucks	Satisfactory
----------------------------------	---------------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
--	---------------------

Comment	
SPURR operator wearing seat belt	-

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Comment	
No cylinders on site.	-

Ladders	Satisfactory
----------------	---------------------

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	Satisfactory
-------------------	---------------------

Comment	
Guardrails in place	

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
---------------------------	---------------------

Comment	
No impalement hazards	

Traffic Control	N/A
------------------------	------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Demolition	N/A
-------------------	------------


Silica Control	Satisfactory
-----------------------	---------------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Unsatisfactory
--------------------------	-----------------------

Comment

<p>Damaged cord will be removed from site.</p>	
--	---

<p>Lockout / Tagout</p>	<p>N/A</p>
--------------------------------	-------------------

<p>Stairways, Ramps, Runways</p>	<p>Satisfactory</p>
---	----------------------------

<p>Other Items (that were observed)</p>	<p>N/A</p>
--	-------------------