

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Inspection:	Fork Lift	
Project	CDI - Visalia, Skyven	Date of Inspection	October 07, 2024	
Inspector Name	Jerod Aaronian	Time of Inspection	08:46 AM	
		NOTES		
lte	19 ems Inspected	19 Satisfactory	0 Unsatisfactory	0 N/A
	INSP	ECTION ITE	MS	
General				
Click "Satisfa	Satisfactory			
	Comment			
Mitsubishi			-	
Is the owners manual in place?				Satisfactory
Is the seat be	elt in place and in safe conditi	on?		Satisfactory
Is the lift's we	eight capacity legible?			Satisfactory
Is the manufa	ncturer name plate in place ar	nd legible?		Satisfactory
Do the fork co	ontrols operate smoothly and	I safely?		Satisfactory
Do the lift's b	rakes work?			Satisfactory
Does the eme	ergency brake work?			Satisfactory

If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory
Is the mast securely in place?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory
Is the lift free of leaks?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Does the horn work?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Is the overheard guard securely in place and in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Is the lift in overall good condition?	Satisfactory