



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Type of Inspection:	Fork Lift
Project	Fresno Shop	Date of Inspection	September 24, 2024
Inspector Name	Westley Portelance	Time of Inspection	01:20 PM

NOTES

19 Items Inspected	17 Satisfactory	0 Unsatisfactory	2 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the fork lift model # in the comments below **Satisfactory**

Comment	
Mitsubishi	-

Is the owners manual in place? **Satisfactory**

Is the seat belt in place and in safe condition? **Satisfactory**

Is the lift's weight capacity legible? **Satisfactory**

Is the manufacturer name plate in place and legible? **Satisfactory**

Do the fork controls operate smoothly and safely? **Satisfactory**

Do the lift's brakes work? **Satisfactory**

Does the emergency brake work? **Satisfactory**

<p>If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?</p>	<p>N/A</p>
<p>Is the mast securely in place?</p>	<p>Satisfactory</p>
<p>Are the fluid levels good? (oil, fuel, water, etc)</p>	<p>Satisfactory</p>
<p>Is the lift free of leaks?</p>	<p>Satisfactory</p>
<p>Are hoses and chains in safe condition?</p>	<p>Satisfactory</p>
<p>Does the horn work?</p>	<p>Satisfactory</p>
<p>Are the headlights and brake lights in good working order?</p>	<p>N/A</p>
<p>Is the overheard guard securely in place and in safe condition?</p>	<p>Satisfactory</p>
<p>Are the forks in safe condition?</p>	<p>Satisfactory</p>
<p>Are the tires in safe condition?</p>	<p>Satisfactory</p>
<p>Is the lift in overall good condition?</p>	<p>Satisfactory</p>

