



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Type of Inspection:	Fork Lift
Project	Fresno Shop	Date of Inspection	October 07, 2024
Inspector Name	Westley Portelance	Time of Inspection	08:20 AM

NOTES

19 Items Inspected	17 Satisfactory	0 Unsatisfactory	2 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory
Comment	
Mitsubishi	-

Is the owners manual in place?	Satisfactory
Is the seat belt in place and in safe condition?	Satisfactory
Is the lift's weight capacity legible?	Satisfactory
Is the manufacturer name plate in place and legible?	Satisfactory
Do the fork controls operate smoothly and safely?	Satisfactory
Do the lift's brakes work?	Satisfactory
Does the emergency brake work?	Satisfactory

<p>If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?</p>	<p>N/A</p>
<p>Is the mast securely in place?</p>	<p>Satisfactory</p>
<p>Are the fluid levels good? (oil, fuel, water, etc)</p>	<p>Satisfactory</p>
<p>Is the lift free of leaks?</p>	<p>Satisfactory</p>
<p>Are hoses and chains in safe condition?</p>	<p>Satisfactory</p>
<p>Does the horn work?</p>	<p>Satisfactory</p>
<p>Are the headlights and brake lights in good working order?</p>	<p>N/A</p>
<p>Is the overheard guard securely in place and in safe condition?</p>	<p>Satisfactory</p>
<p>Are the forks in safe condition?</p>	<p>Satisfactory</p>
<p>Are the tires in safe condition?</p>	<p>Satisfactory</p>
<p>Is the lift in overall good condition?</p>	<p>Satisfactory</p>

