

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	Traced by Carety Compilarioe App			· · · · · ·	
Company	Bay City Boiler	Type of Inspection:	Scissor lift		
Project	Fresno Shop	Date of Inspection	October 15, 2024		
Inspector Name	Ralph Jackson	Time of Inspection	09:09 AM		
NOTES					
lte	15 ems Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A	
INSPECTION ITEMS					
General					
Click "Satisfa	Satisfactory				
Is the owners manual in place?				Satisfactory	
Is the back up alarm or moving alarm working?				Satisfactory	
Are the guardrails in place?				Satisfactory	
Are the tires in safe condition?				Satisfactory	
Is the emergency stop button working?				Satisfactory	
Are the indicator lights working?				Satisfactory	
Does the plat	Satisfactory				

Satisfactory

Perform a platform control check. Does everything operate smoothly?

Perform a ground control check. Does everything operate smoothly?	Satisfactory
Is the lift in overall good condition and the platform clean?	Satisfactory
Are the structure, pins, scissors and covers in good condition?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Does the horn work?	Satisfactory
Check the batteries. Is the water level sufficient?	Satisfactory