

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Inspection:	Fork Lift		
Project	Fresno Shop	Date of Inspection	November 19, 2024		
Inspector Name	Lucas Baro	Time of Inspection	11:33 AM		
		NOTES			
lte	19 ems Inspected	17 Satisfactory	0 Unsatisfactory	2 N/A	
	INSP	ECTION ITE	MS		
General					
Click "Satisfa	Satisfactory				
Comment					
Mitsubishi			-		
Is the owners	manual in place?			Satisfactory	
Is the seat belt in place and in safe condition? Satisfactory					
Is the lift's we	eight capacity legible?			Satisfactory	
Is the manufa	cturer name plate in place ar	nd legible?		Satisfactory	
Do the fork co	ontrols operate smoothly and	I safely?		Satisfactory	
Do the lift's b	rakes work?			Satisfactory	
Does the eme	ergency brake work?			Satisfactory	

If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	N/A
Is the mast securely in place?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory
Is the lift free of leaks?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Does the horn work?	Satisfactory
Are the headlights and brake lights in good working order?	N/A
Is the overheard guard securely in place and in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Is the lift in overall good condition?	Satisfactory