



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Type of Inspection:	Fork Lift
Project	Fresno Shop	Date of Inspection	November 22, 2024
Inspector Name	Moises Hernandez	Time of Inspection	08:24 AM

NOTES

19 Items Inspected	19 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the fork lift model # in the comments below **Satisfactory**

Comment	
Mitsubishi	-

Is the owners manual in place? **Satisfactory**

Is the seat belt in place and in safe condition? **Satisfactory**

Is the lift's weight capacity legible? **Satisfactory**

Is the manufacturer name plate in place and legible? **Satisfactory**

Do the fork controls operate smoothly and safely? **Satisfactory**

Do the lift's brakes work? **Satisfactory**

Does the emergency brake work? **Satisfactory**

If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory
Is the mast securely in place?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory
Is the lift free of leaks?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Does the horn work?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Is the overheard guard securely in place and in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Is the lift in overall good condition?	Satisfactory

