



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Type of Inspection:	BC Safety Inspection
Project	Kaiser Modesto	Date of Inspection	December 31, 2025
Inspector Name	Jon Bruland	Time of Inspection	07:49 AM

NOTES

16
Items Inspected

11
Satisfactory

0
Unsatisfactory

5
N/A

Travis and R2 investigating boiler exhaust leaks and combustion issues

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Is Personal Protective Equipment being worn as required?: Eye, ear, glove, respirator, shoes, and face shield? **Satisfactory**

Are scaffolding safety procedures being followed and inspected?: Fully planked, guardrails in place, toe boards, and ladders? **N/A**

Are hand and power tools being used safely? Are guards installed on tools? **Satisfactory**

Is good housekeeping being maintained?: Clean work area and sufficient lighting in work area? **Satisfactory**

Is fall protection in place where required? Fall harness and lanyard inspected?	N/A
Are ladders being used safely? Was the ladder inspected and in good condition?	N/A
Are confined space safety procedures being followed?: Permit posted? Was the customer informed of the operation?	N/A
Hot work permit posted? Is the welding screen utilized and fire watch established?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Are boom lifts and other aerial devices being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are all other tasks being performed safely?	Satisfactory
Is lockout/tagout included in the operation? Are proper procedures being followed?	Satisfactory