



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	Chesmar General Construction
Project	719 - Bryson	Date of Inspection	January 24, 2025
Inspector Name	Levon Whitmyer	Time of Inspection	10:23 AM

NOTES

18 Items Inspected	11 Satisfactory	0 Unsatisfactory	7 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)?	Satisfactory
Comment	
Portable station. No model	-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.)	N/A
Is drinking water sufficient for the number of workers?	Satisfactory
Is safety signage in place around the community?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	Satisfactory
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping maintained on interior & exterior of home?	Satisfactory

Is fall protection in place where required?

N/A

Is trenching & excavation work being done safely and marked off or protected?

N/A

Is there clear and safe access to each home?

Satisfactory

Are ladders in good condition and being used correctly?

Satisfactory

Are pump trucks and aerial devices being used safely?

N/A

Are proper face coverings being worn when necessary?

N/A

Are Temporary Meter Loops in good condition and being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Are flammable liquids being stored and used in a safe manner?

N/A

Are all other tasks being performed safely?

Satisfactory