



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Chesmar Homes: Austin	<b>Type of Inspection:</b>	Chesmar General Construction
<b>Project</b>	733 - 203 - Brooklands	<b>Date of Inspection</b>	July 03, 2024
<b>Inspector Name</b>	Brandon Cinalli	<b>Time of Inspection</b>	04:59 PM

## NOTES

<b>18</b> Items Inspected	<b>13</b> Satisfactory	<b>0</b> Unsatisfactory	<b>5</b> N/A
------------------------------	---------------------------	----------------------------	-----------------

## INSPECTION ITEMS

### General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.) **Satisfactory**

Is drinking water sufficient for the number of workers? **Satisfactory**

Is safety signage in place around the community? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping maintained on interior & exterior of home? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

**Is trenching & excavation work being done safely and marked off or protected?**

**N/A**

**Is there clear and safe access to each home?**

**Satisfactory**

**Are ladders in good condition and being used correctly?**

**Satisfactory**

**Are pump trucks and aerial devices being used safely?**

**N/A**

**Are proper face coverings being worn when necessary?**

**Satisfactory**

**Are Temporary Meter Loops in good condition and being used safely?**

**N/A**

**Are roofing operations being performed safely?**

**N/A**

**Are flammable liquids being stored and used in a safe manner?**

**Satisfactory**

**Are all other tasks being performed safely?**

**Satisfactory**