

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	General Construction
Project	745 - NorthFork	Date of Inspection	April 19, 2024
Inspector Name	Edmond Trejo	Time of Inspection	04:25 PM

## SUMMARY OF INSPECTION INSPECTION ITEMS

INSECTION ITEMS			
General			
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	N/A		
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	N/A		
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory		
Are emergency and labor law postings in place?	N/A		
Is Personal Protective Equipment being worn as required?	N/A		
Are scaffolding safety procedures being followed?	N/A		
Are hand and power tools being used safely?	Satisfactory		
Is good housekeeping being maintained?	N/A		
Is fall protection in place where required?	N/A		
Is trenching & excavation work being done safely?	N/A		

Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory