



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	Chesmar General Construction
Project	783 - Blackhawk	Date of Inspection	June 19, 2024
Inspector Name	Michael Kinsey	Time of Inspection	01:49 PM

NOTES

18
Items Inspected

17
Satisfactory

1
Unsatisfactory

0
N/A

Scaffolding not safe

INSPECTION ITEMS

General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.) **Satisfactory**

Is drinking water sufficient for the number of workers? **Satisfactory**

Is safety signage in place around the community? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **Unsatisfactory**

Comment

Scaffolding not safe



Are hand and power tools being used safely?

Satisfactory

Is good housekeeping maintained on interior & exterior of home?

Satisfactory

Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely and marked off or protected?

Satisfactory

Is there clear and safe access to each home?

Satisfactory

Are ladders in good condition and being used correctly?

Satisfactory

Are pump trucks and aerial devices being used safely?

Satisfactory

Are proper face coverings being worn when necessary?

Satisfactory

Are Temporary Meter Loops in good condition and being used safely?

Satisfactory

Are roofing operations being performed safely?

Satisfactory

Are flammable liquids being stored and used in a safe manner?

Satisfactory

Are all other tasks being performed safely?

Satisfactory