



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	Chesmar General Construction
Project	Briarwood 45s	Date of Inspection	January 31, 2025
Inspector Name	Brandon Cinalli	Time of Inspection	04:52 PM

NOTES

18 Items Inspected	13 Satisfactory	1 Unsatisfactory	4 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.)	Satisfactory
Is drinking water sufficient for the number of workers?	Satisfactory
Is safety signage in place around the community?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping maintained on interior & exterior of home?	Satisfactory
Is fall protection in place where required?	Satisfactory

Is trenching & excavation work being done safely and marked off or protected?

N/A

Is there clear and safe access to each home?

Satisfactory

Are ladders in good condition and being used correctly?

Unsatisfactory

Comment

-

Are pump trucks and aerial devices being used safely?

N/A

Are proper face coverings being worn when necessary?

Satisfactory

Comment

Framers wearing glasses when making cuts and nailing

-

Are Temporary Meter Loops in good condition and being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Are flammable liquids being stored and used in a safe manner?

Satisfactory

Are all other tasks being performed safely?

Satisfactory