



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	Chesmar General Construction
Project	Highcrest Meadows	Date of Inspection	June 10, 2024
Inspector Name	Hannah Elkhay	Time of Inspection	09:02 AM

NOTES

18
Items Inspected

14
Satisfactory

0
Unsatisfactory

4
N/A

INSPECTION ITEMS

General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.) **Satisfactory**

Is drinking water sufficient for the number of workers? **Satisfactory**

Is safety signage in place around the community? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping maintained on interior & exterior of home? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

Is trenching & excavation work being done safely and marked off or protected?

Satisfactory

Is there clear and safe access to each home?

Satisfactory

Are ladders in good condition and being used correctly?

Satisfactory

Are pump trucks and aerial devices being used safely?

N/A

Are proper face coverings being worn when necessary?

Satisfactory

Are Temporary Meter Loops in good condition and being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Are flammable liquids being stored and used in a safe manner?

N/A

Are all other tasks being performed safely?

Satisfactory