



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Chesmar Homes: Austin	Type of Inspection:	Chesmar General Construction
Project	Highcrest Meadows	Date of Inspection	July 11, 2024
Inspector Name	Hannah Elkhay	Time of Inspection	09:54 AM

NOTES

18
Items Inspected

13
Satisfactory

0
Unsatisfactory

5
N/A

INSPECTION ITEMS

General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.) **Satisfactory**

Is drinking water sufficient for the number of workers? **Satisfactory**

Is safety signage in place around the community? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **Satisfactory**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping maintained on interior & exterior of home? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

Is trenching & excavation work being done safely and marked off or protected?

N/A

Is there clear and safe access to each home?

Satisfactory

Are ladders in good condition and being used correctly?

Satisfactory

Are pump trucks and aerial devices being used safely?

N/A

Are proper face coverings being worn when necessary?

Satisfactory

Are Temporary Meter Loops in good condition and being used safely?

N/A

Are roofing operations being performed safely?

N/A

Are flammable liquids being stored and used in a safe manner?

N/A

Are all other tasks being performed safely?

Satisfactory