



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Chesmar Homes: Austin	<b>Type of Inspection:</b>	Chesmar General Construction
<b>Project</b>	Highcrest Meadows	<b>Date of Inspection</b>	September 13, 2024
<b>Inspector Name</b>	Hannah Elkhay	<b>Time of Inspection</b>	01:02 PM

## NOTES

18 Items Inspected	11 Satisfactory	1 Unsatisfactory	6 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Is emergency equipment available, including a first aid kit (stocked) and a fire extinguisher (inspected)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings, Community Safety Meetings, labor laws, Emergency Locations, Emergency Numbers.)	Satisfactory
Is drinking water sufficient for the number of workers?	Satisfactory
Is safety signage in place around the community?	Unsatisfactory
<b>Comment</b>	
I need to hang the hard hat signs	-
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	Satisfactory
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping maintained on interior & exterior of home?	Satisfactory

**Is fall protection in place where required?**

**N/A**

**Is trenching & excavation work being done safely and marked off or protected?**

**N/A**

**Is there clear and safe access to each home?**

**Satisfactory**

**Are ladders in good condition and being used correctly?**

**Satisfactory**

**Are pump trucks and aerial devices being used safely?**

**N/A**

**Are proper face coverings being worn when necessary?**

**Satisfactory**

**Are Temporary Meter Loops in good condition and being used safely?**

**N/A**

**Are roofing operations being performed safely?**

**N/A**

**Are flammable liquids being stored and used in a safe manner?**

**N/A**

**Are all other tasks being performed safely?**

**Satisfactory**