



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|----------------------|----------------------------|--------------|
| Company | Concrete North, Inc. | Type of Inspection: | Scissor lift |
| Project | 23-005 Switch | Date of Inspection | May 06, 2024 |
| Inspector Name | Richard Smith | Time of Inspection | 06:18 AM |

NOTES

| | | | |
|-----------------------|--------------------|---------------------|----------|
| 15 Items Inspected | 15 Satisfactory | 0 Unsatisfactory | 0 N/A |
|-----------------------|--------------------|---------------------|----------|

INSPECTION ITEMS

General

Click "Satisfactory" and enter the model # in the comments section below **Satisfactory**

| Comment | |
|-----------------|---|
| Skyjack iii3226 | - |

Is the owners manual in place? **Satisfactory**

Is the back up alarm or moving alarm working? **Satisfactory**

Are the guardrails in place? **Satisfactory**

Are the tires in safe condition? **Satisfactory**

Is the emergency stop button working? **Satisfactory**

Are the indicator lights working? **Satisfactory**

Does the platform extension open and close smoothly and lock into place? **Satisfactory**

Perform a platform control check. Does everything operate smoothly?

Satisfactory

Perform a ground control check. Does everything operate smoothly?

Satisfactory

Is the lift in overall good condition and the platform clean?

Satisfactory

Are the structure, pins, scissors and covers in good condition?

Satisfactory

Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?

Satisfactory

Does the horn work?

Satisfactory

Check the batteries. Is the water level sufficient?

Satisfactory

