

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift
Project	23-005 Switch	Date of Inspection	May 16, 2024
Inspector Name	Richard Smith	Time of Inspection	01:45 AM

NOTES						
22	<b>20</b>	<b>0</b>	<b>2</b>			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

## **INSPECTION ITEMS**

## General Click "Satisfactory" and enter the reach lift model # in the comments below **Satisfactory** Comment JLG 10054 \_ Is the owners manual in place? Satisfactory Is any rigging being used tagged, rated for the loads being handled, and rigged by a N/A qualified rigger? Does the emergency brake work? Satisfactory Do the lift's brakes work? Satisfactory Do the fork controls operate smoothly and safely? Satisfactory is the manufacturer name plate in place and legible? Satisfactory Is the load chart in place? Satisfactory

May 16, 2024

Is the lift's level working properly?	Satisfactory
Does the horn work?	Satisfactory
Do all machine / fork controls operate smoothly?	Satisfactory
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A
Is the mast securely in place?	Satisfactory
Is the lift in overall good condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Is the operators cab securely in place and in safe condition?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Does the horn work?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Is the lift free of leaks?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory

Concrete North, Inc. | 23-005 Switch