



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Concrete North, Inc.	<b>Type of Inspection:</b>	Boom Lift
<b>Project</b>	23-005 Switch	<b>Date of Inspection</b>	May 16, 2024
<b>Inspector Name</b>	Richard Smith	<b>Time of Inspection</b>	01:46 AM

## NOTES

14 Items Inspected	14 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Click "Satisfactory" and enter the boom lift model # in the comments below **Satisfactory**

Comment	
Skyjack iii3226	-

Is the lift in overall good condition and the platform clean? **Satisfactory**

Are there full body harnesses available with the correct lanyard for those working in the basket? **Satisfactory**

Are the indicator lights working? **Satisfactory**

Perform a platform control check. Does everything operate smoothly? **Satisfactory**

Perform a ground control check. Does everything operate smoothly? **Satisfactory**

Are the tires in safe condition? **Satisfactory**

Are the platform anchor point(s) in place and clearly labeled? **Satisfactory**

**Are the guardrails and platform door in securely in place?**

**Satisfactory**

**Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?**

**Satisfactory**

**Is the owners manual in place?**

**Satisfactory**

**Are the structure, pins and covers in good condition?**

**Satisfactory**

**Does the horn work?**

**Satisfactory**

**Is the moving alarm working?**

**Satisfactory**

