

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Boom Lift
Project	23-005 Switch	Date of Inspection	May 16, 2024
Inspector Name	Richard Smith	Time of Inspection	01:46 AM

NOTES						
14	<b>14</b>	<b>0</b>	<b>0</b>			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

## **INSPECTION ITEMS**

## General Click "Satisfactory" and enter the boom lift model # in the comments below **Satisfactory** Comment Skyjack sj46aj Is the lift in overall good condition and the platform clean? Satisfactory Are there full body harnesses available with the correct lanyard for those working in Satisfactory the basket? Are the indicator lights working? **Satisfactory** Perform a platform control check. Does everything operate smoothly? Satisfactory Perform a ground control check. Does everything operate smoothly? Satisfactory Are the tires in safe condition? Satisfactory Are the platform anchor point(s) in place and clearly labeled? Satisfactory

Are the guardrails and platform door in securely in place?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Is the owners manual in place?	Satisfactory
Are the structure, pins and covers in good condition?	Satisfactory
Does the horn work?	Satisfactory
Is the moving alarm working?	Satisfactory

Concrete North, Inc. | 23-005 Switch