

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift
Project	24-013 Tahoe Donner Ski Lodge	Date of Inspection	July 08, 2024
Inspector Name	Richard Smith	Time of Inspection	09:40 AM

NOTES						
22	20	0	2			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

INSPECTION ITEMS

General		
Click "Satisfactory" and enter the reach lift model # in the com	nents below Sa	tisfactory
Comment		
JCB 510-56	-	
Is the owners manual in place?	Sa	tisfactory
Is any rigging being used tagged, rated for the loads being han qualified rigger?	dled, and rigged by a	N/A
Does the emergency brake work?	Sa	tisfactory
Does the emergency brake work? Do the lift's brakes work?		tisfactory tisfactory
	Sa	
Do the lift's brakes work?	Sa Sa	tisfactory

Jul 08, 2024

Is the lift's level working properly?	Satisfactory
Does the horn work?	Satisfactory
Do all machine / fork controls operate smoothly?	Satisfactory
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A
Is the mast securely in place?	Satisfactory
Is the lift in overall good condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Is the operators cab securely in place and in safe condition?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Does the horn work?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Is the lift free of leaks?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory