

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift		
Project	24-013 Tahoe Donner Ski Lodge	Date of Inspection	September 16, 2024		
Inspector Name	Richard Smith	Time of Inspection	07:03 AM		
NOTES					
lte	22 ems Inspected	<b>20</b> Satisfactory	<b>0</b> Jnsatisfactory	<b>2</b> N/A	
	·				
INSPECTION ITEMS					
General					
Click "Satisfa	Click "Satisfactory" and enter the reach lift model # in the comments below  Satisfactory				
Comment					
JCB 510-56			-		
Is the owners	manual in place?			Satisfactory	
Is any rigging being used tagged, rated for the loads being handled, and rigged by a qualified rigger?				N/A	
Does the emergency brake work?				Satisfactory	
Do the lift's b	rakes work?			Satisfactory	
Do the fork controls operate smoothly and safely?				Satisfactory	
is the manufacturer name plate in place and legible?				Satisfactory	
Is the load ch	art in place?			Satisfactory	

Is the lift's level working properly?	Satisfactory
Does the horn work?	Satisfactory
Do all machine / fork controls operate smoothly?	Satisfactory
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A
Is the mast securely in place?	Satisfactory
Is the lift in overall good condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Is the operators cab securely in place and in safe condition?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Does the horn work?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Is the lift free of leaks?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory