

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	erated by Sarety Compilance App	WW.54	ictycomphanic	on www.sarci		
Company	Concrete North, Inc.		Type of Inspection:	Power Truck	- Reach Lift	
Project	24-013 Tahoe Donner Ski Lodge		Date of Inspection	September 19	9, 2024	
Inspector Name	Richard Smith		Time of Inspection	06:38 AM		
		NO	TEC			
		NO	TES			
lte	22 ems Inspected		20 sfactory	0 Unsatisfactory	2 N/A	
INSPECTION ITEMS						
General						
Click "Satisfactory" and enter the reach lift model # in the comments below						
Comment						
JCB 510-56					-	
Is the owners	manual in place?				Satisfactory	
Is any rigging being used tagged, rated for the loads being handled, and rigged by a qualified rigger?					by a N/A	
Does the eme	ergency brake work?				Satisfactory	
Do the lift's b	rakes work?				Satisfactory	
Do the fork controls operate smoothly and safely?					Satisfactory	
is the manufa	cturer name plate in place an	d legible	e?		Satisfactory	
Is the load ch	art in place?				Satisfactory	

Is the lift's level working properly?	Satisfactory
Does the horn work?	Satisfactory
Do all machine / fork controls operate smoothly?	Satisfactory
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A
Is the mast securely in place?	Satisfactory
Is the lift in overall good condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Is the operators cab securely in place and in safe condition?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Does the horn work?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Is the lift free of leaks?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory