



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift
Project	24-013 Tahoe Donner Ski Lodge	Date of Inspection	October 04, 2024
Inspector Name	Richard Smith	Time of Inspection	07:06 AM

NOTES

22 Items Inspected	20 Satisfactory	0 Unsatisfactory	2 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the reach lift model # in the comments below **Satisfactory**

Comment	
Xtreme xrm 1045	-

Is the owners manual in place? **Satisfactory**

Is any rigging being used tagged, rated for the loads being handled, and rigged by a qualified rigger? **N/A**

Does the emergency brake work? **Satisfactory**

Do the lift's brakes work? **Satisfactory**

Do the fork controls operate smoothly and safely? **Satisfactory**

is the manufacturer name plate in place and legible? **Satisfactory**

Is the load chart in place? **Satisfactory**

Is the lift's level working properly?	Satisfactory
Does the horn work?	Satisfactory
Do all machine / fork controls operate smoothly?	Satisfactory
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A
Is the mast securely in place?	Satisfactory
Is the lift in overall good condition?	Satisfactory
Are the tires in safe condition?	Satisfactory
Are the forks in safe condition?	Satisfactory
Is the operators cab securely in place and in safe condition?	Satisfactory
Are the headlights and brake lights in good working order?	Satisfactory
Does the horn work?	Satisfactory
Are hoses and chains in safe condition?	Satisfactory
Is the lift free of leaks?	Satisfactory
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory

