

SAFETY INSPECTION REPORT

CONDUCTED FOR:
D.R. Horton, Inc. - Reno

PROJECT:
Arroyo Crossing - The Meadows



INSPECTION TYPE:
General Construction

INSPECTOR : SHAWN ST. PETERS
DATE : NOVEMBER 30, 2024
CITY : RENO
STATE : NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	35 Satisfactory	3 Unsatisfactory	15 N/A
------------------------------	---------------------------	----------------------------	------------------

Arroyo Crossing Meadows Project on Grassy Plains and Wandering Way with several homes under construction, some recently stuccoed and others under construction, and getting prepped for stucco. In addition forms in place for concrete pads for additional homes. Housekeeping on the worksite is very good. Workers wearing appropriate PPE with exception of Safety Glasses. Scaffolding in good condition and being inspected daily.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Comment	
Workers have adequate water and shade in the garages for breaks.	-
Safety Data Sheets	N/A
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory

First Aid / CPR Certification	Satisfactory
Comment	
First Aid CPR and AED training completed	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
Comment	
Fire Extinguishers are in good working condition.	-

First Aid Kit(s)	Satisfactory
Comment	
Hurts Aid Kits are available.	-

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
Comment	
Workers have porta potties available when needed.	-

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
Comment	
Garage areas is being utilized for shade for the workers.	-

Tools & Equipment

Power Tools	Unsatisfactory
Comment	
Safety glasses need to be worn when operating power saw.	-

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	Satisfactory
------------------------------	---------------------

Pneumatic Nailers	Satisfactory
--------------------------	---------------------

Mobile Elevated Work Platforms (MEWP's)	Satisfactory
--	---------------------

Powered Industrial Trucks	Satisfactory
----------------------------------	---------------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
Comment	
Extension ladders were tied off	-

Operations

Personal Protective Equipment	Unsatisfactory
Comment	
Safety glasses needed for the workers	-

Trenching & Excavation	Satisfactory
Fall Protection	Satisfactory
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Unsatisfactory
Comment	
Housekeeping an opportunity with many potential trip hazards. Also need dumpster emptied as it is full.	-
Demolition	N/A
Silica Control	Satisfactory
Comment	
Water truck onsite for silica dust control.	-
Rigging Operations	N/A

Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A