## **SAFETY INSPECTION REPORT**

**CONDUCTED FOR:** D.R. Horton, Inc. - Reno

## **PROJECT:**

Arroyo Crossing- The Summit



**INSPECTION TYPE:** General Construction

INSPECTOR : SHAWN ST. PETERS DATE : AUGUST 09, 2024 CITY : RENO STATE : NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION				
53	<b>39</b>	<b>0</b>	<b>14</b>	
Items Inspected	Satisfactory	Unsatisfactory	N/A	

#### SUMMARY OF INSPECTION

Arroyo Crossing- The Summit homes under framing construction and with new poured concrete pads for additional construction. DNA Carpentry workers onsite working safely during my worksite walk. Workers were wearing their PPE. Scaffolding is in good condition. Housekeeping and storage of materials and walking working areas in good condition. Campbell's excavation onsite with backhoe and skid steer, and dump truck. In the process of placement of underground, piping, and new trenching and excavation. Workers were wearing PPE Safety Glasses, and hard hats.

# **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory

Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Comment	
First Aid Training has been completed.	-
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
Comment	
Fire Extinguishers have been inspected and in good condition.	-
First Aid Kit(s)	Satisfactory
Comment	
First Aid are available.	-
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
	Satisfactory Satisfactory
Restrooms Hand Washing Stations	
Restrooms	Satisfactory

**Fall Protection** 

Satisfactory

Comment	
Garage areas is being utilized for shade for the workers.	-
Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Comment	
Extension ladders are tied off.	-
Operations	
Personal Protective Equipment	Satisfactory
Comment	
Safety glasses being worn by workers on the worksite.	-
Trenching & Excavation	Satisfactory

Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Demolition	Satisfactory
Silica Control	Satisfactory
Comment	
Water truck onsite for silica dust control.	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A

### Stairways, Ramps, Runways

#### Other Items (that were observed)

Aug 09, 2024

Satisfactory

N/A