

SAFETY INSPECTION REPORT

CONDUCTED FOR:
D.R. Horton, Inc. - Reno

PROJECT:
Arroyo Crossing- The Summit



INSPECTION TYPE:
General Construction

INSPECTOR : SHAWN ST. PETERS
DATE : OCTOBER 06, 2024
CITY : RENO
STATE : NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	39 Satisfactory	0 Unsatisfactory	14 N/A
------------------------------	---------------------------	----------------------------	------------------

SUMMARY OF INSPECTION

Arroyo Crossing- The Summit on wandering way two homes recently stuccoed and two more prepped for stucco and two under framing construction and with new poured pads for additional construction. DNA Carpentry workers onsite working safely during my worksite walk. Workers were wearing their PPE. Scaffolding is in good condition. Housekeeping and storage of materials and walking working areas in good condition. Workers were wearing PPE Safety Glasses, high visibility clothing and hard hats.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Comment	
Workers have adequate water and shade with the garages to cool down with the warm weather.	-
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory

Labor Law Postings	Satisfactory
Comment	
Signage is posted at the front of the project.	-

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

First Aid / CPR Certification	Satisfactory
Comment	
First Aid Training has been completed.	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--------------------------------------------------	------------

Fire Extinguisher(s)	Satisfactory
Comment	
Fire Extinguishers have been inspected and in good condition.	-

First Aid Kit(s)	Satisfactory
Comment	
First Aid are available.	-

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--------------------------------------------------	------------

General Items

Restrooms	Satisfactory
Comment	
The project has adequate porta potties for the work crew	-

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Waste Containers	Satisfactory
Comment	
Dumpster has been emptied	-

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
Comment	
Garage areas is being utilized for shade for the workers.	-

Tools & Equipment

Power Tools	Satisfactory
Comment	
Safety glasses being worn when operating power saw	-

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	Satisfactory
------------------------------	---------------------

Pneumatic Nailers	Satisfactory
--------------------------	---------------------

Mobile Elevated Work Platforms (MEWP's)	N/A
------------------------------------------------	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
----------------------------------------------------------	---------------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
Comment	

Extension ladders are tied off.	-
---------------------------------	---

Operations

Personal Protective Equipment	Satisfactory
Comment	
Safety glasses being worn by workers on the worksite.	-

Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Fall Protection	Satisfactory
------------------------	---------------------

Guardrails	Satisfactory
-------------------	---------------------

Floor / Wall Openings	Satisfactory
------------------------------	---------------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
---------------------------	---------------------

Traffic Control	Satisfactory
------------------------	---------------------

Roofing Operations	Satisfactory
---------------------------	---------------------

Housekeeping	Satisfactory
---------------------	---------------------

Demolition	Satisfactory
-------------------	---------------------

Silica Control	Satisfactory
-----------------------	---------------------

Comment

Water truck onsite for silica dust control.

-

Rigging Operations**N/A****Hot Work****N/A****Electrical Safety****Satisfactory****Lockout / Tagout****N/A****Stairways, Ramps, Runways****Satisfactory****Other Items (that were observed)****N/A**