

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
D.R. Horton, Inc. - Reno

**PROJECT:**  
Nevada Sky Project



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** SHAWN ST. PETERS  
**DATE :** NOVEMBER 29, 2024  
**CITY :** FERNLEY  
**STATE :** NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>39</b> Satisfactory	<b>0</b> Unsatisfactory	<b>14</b> N/A
------------------------------	---------------------------	----------------------------	------------------

**Nevada Sky Project**

Many homes under construction at various phases concrete placement, framing, and prepping for stucco. New model homes with new stucco looks good both models and have been painted on exterior. Housekeeping is very good no debris left on the ground. Four workers on site doing framing. Workers were wearing all of there appropriate PPE including safety glasses. No hazards identified during my worksite visit. Scaffolding is in good condition and is being inspected daily. Many locations are getting prepped with level building lots.

## INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	
Workers have water and shade for the warm weather conditions.	-
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>OSHA Permits</b>	<b>Satisfactory</b>

<b>Labor Law Postings</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
<b>Comment</b>	
First Aid CPR & AED Training up to date	-

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
Fire extinguishers available and inspected	-

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
<b>Comment</b>	
Workers have porta potties available for restrooms.	-

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	
Garage areas is being utilized for shade.	-

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Powder Actuated Tools</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Pneumatic Nailers</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Mobile Elevated Work Plarforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>Satisfactory</b>
--	---------------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

<b>Comment</b>	
Extension ladders are tied off.	-

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Trenching &amp; Excavation</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>Fall Protection</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Guardrails</b>	<b>Satisfactory</b>
<b>Floor / Wall Openings</b>	<b>Satisfactory</b>
<b>Supported Scaffolding</b>	<b>Satisfactory</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Traffic Control</b>	<b>Satisfactory</b>
<b>Roofing Operations</b>	<b>Satisfactory</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>Satisfactory</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>

