SAFETY INSPECTION REPORT

CONDUCTED FOR:

D.R. Horton, Inc. - Reno

PROJECT:

Stonebrook - Links



INSPECTION TYPE:

General Construction

INSPECTOR: SHAWN ST. PETERS DATE: SEPTEMBER 06, 2024

CITY: SPARKS STATE: NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	34	2 Unsatisfactory	17
Items Inspected	Satisfactory		N/A

Stonebrook Links continue with construction phases three homes under construction framing phase and two additional concrete pads recently placed. Four workers on site two on concrete and the rest on framing. The job site has housekeeping opportunities with walking trip fall hazards with miscellaneous work material debris. PPE Safety glasses needed for the employees with potential of dust or small particles getting into the workers eyes.

INSPECTION ITEMS		
Documentation		
Site Contact	Satisfactory	
Safety Program (Including IIPP)	Satisfactory	
Heat Illness Prevention Program	Satisfactory	
Comment		
Workers have water and shade when taking breaks.	-	
Safety Data Sheets	Satisfactory	
Daily Inspections	Satisfactory	
Tailgate Meetings	Satisfactory	
Sub-Contractor Meetings	Satisfactory	
OSHA Permits	Satisfactory	
Labor Law Postings	Satisfactory	

Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Comment	
Workers have First Aid CPR and AED training	-
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
Comment	
Fire extinguishers inspected and available.	-
First Aid Kit(s)	Satisfactory
Comment	
First Aid kits available on the worksite.	-
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	Satisfactory
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory

Zint Herteri, iner Henri Feteriosi een Zinte	30p 30, 2021
Comment	
Garage areas used for shade for the workers	-
Tools & Equipment	
Power Tools	Satisfactory
Comment	
Safety Glasses needed when using portable saw	-
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Comment	
Ladders extension were tied off during my inspection	-
Operations	
Personal Protective Equipment	Unsatisfactory
0	

Comment

Safety Glasses needed for the workers.

Trenching & Excavation	N/A
Fall Protection	Satisfactory
Comment	
Workers were wearing the proper pfas personal fall arrest equipment	-
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	Satisfactory
Comment	
Scaffolding was in good condition when inspected.	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	N/A
Roofing Operations	Satisfactory
Housekeeping	Unsatisfactory
Comment	
Housekeeping on the project is an opportunity	-
Demolition	N/A
Silica Control	Satisfactory

Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A