

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
D.R. Horton, Inc. - Reno

**PROJECT:**  
Stonebrook - Links



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** SHAWN ST. PETERS  
**DATE :** OCTOBER 06, 2024  
**CITY :** SPARKS  
**STATE :** NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>34</b> Satisfactory	<b>2</b> Unsatisfactory	<b>17</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Stonebrook Links continue with construction phases two homes under construction framing phase and two additional concrete pads recently placed. Four workers on site two on concrete and the rest on framing. The job site is clean and scaffolding is inspected and good condition on Marjorite drive. PPE Safety glasses needed for the employees with potential of dust or small particles getting into the workers eyes.

## INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	
Workers have water and shade when taking breaks.	-
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Emergency / Other Postings</b>	<b>Satisfactory</b>

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
<b>Comment</b>	
Workers have First Aid CPR and AED training	-

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
Fire extinguishers inspected and available.	-

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
First Aid kits available on the worksite.	-

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>Satisfactory</b>
--	---------------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	

Garage areas used for shade for the workers	-
---	---

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Comment</b>	
----------------	--

Safety Glasses needed when using portable saw	-
---	---

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

<b>Comment</b>	
----------------	--

Ladders extension were tied off during my inspection	-
--	---

## Operations

<b>Personal Protective Equipment</b>	<b>Unsatisfactory</b>
--------------------------------------	-----------------------

<b>Comment</b>	
----------------	--

Safety Glasses needed for the workers.	-
--	---

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>Satisfactory</b>
<b>Comment</b>	
Workers were wearing the proper pfas personal fall arrest equipment	-
<b>Guardrails</b>	<b>Satisfactory</b>
<b>Floor / Wall Openings</b>	<b>Satisfactory</b>
<b>Supported Scaffolding</b>	<b>Satisfactory</b>
<b>Comment</b>	
Scaffolding was in good condition when inspected.	-
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Traffic Control</b>	<b>N/A</b>
<b>Roofing Operations</b>	<b>Satisfactory</b>
<b>Housekeeping</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
Housekeeping on the project is an opportunity	-
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>Satisfactory</b>
<b>Rigging Operations</b>	<b>N/A</b>

<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>